

FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management Solid Waste Section

UNIT TYPE:											
Lined MSWLF	LCID	YW	Transfer	Compost	SLAS	X	COUNTY: Wilson				
Closed MSWLF	HHW	White goods	Incin	T&P	FIRM		PERMIT NO.: SLAS-98-08				
CDLF	Tire T&P / Collection	Tire Monofill	Industrial Landfill	DEMO	SDTF		FILE TYPE: COMPLIANCE				

FACILITY NAME AND ADDRESS:

David Newsome D & D Septic LLC 441 Buck Newsome Road Fremont, NC 27830

GPS COORDINATES: <u>N</u>: <u>35.59874</u> <u>W</u>: <u>-77.87832</u>

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: David Newsome Telephone: 252-206-6802

Email address: Fax: *252-242-4268*

FACILITY CONTACT ADDRESS:

Same as above.

PARTICIPANTS: Chester Cobb

STATUS OF PERMIT: Active EXPIRES: 5/11/2016

PURPOSE OF SITE VISIT: Routine

STATUS OF PAST NOTED VIOLATIONS:

No violations noted on the previous inspection conducted on 1/4/12.

OBSERVED VIOLATIONS:

NONE

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

- 1. The appropriate signage was present at the entrance to the dewatering facility and by the path beside Field 3.
- 2. The access road was in good shape.
- 3. Markers need to be placed back up along the southern edge (next to the field of sweet potatoes) of Field 3. Markers will need to be 50 ft from the sweet potatoes.
- 4. No discharges noticed outside of the permitted field boundaries.
- 5. No spot dumps or thick applications noticed.
- 6. Bermudagrass has been planted in Field #3. Crabgrass issue in all fields. Some other grass present in Field #3 such as crowfoot grass.
- 7. pH of septage not checked. No application at time of inspection.
- 8. No objectionable odors noticed today.
- 9. Outside markers to Field #3 need to be 50 ft from the sweet potatoes. No other setback issues noticed.
- 10. Records not checked.
- 11. Need to place the outside markers to Field #3 back up. Markers will need to be placed at least 50 ft from the sweet potatoes. Did not notice any recent application to this field. Area within Pull #9 seems to have recover from the application of fatty acids (see 11-3-11 audit report). Bermudagrass had been planted and was starting to spread.

Please contact me if you have any questions or concerns regarding this inspection report.

Chesto R. Coll						
Chester R. Cobb						
Regional Representative						

Phone: (919) 707-8283

Sent on: 7/25/13	Email	Hand delivery	X	US Mail	Certified No. [_]